192			
No.	Particulars	Unit	Quantity
1, 4			
4			
	Part III—Installation of calling bells.		7
	Sumbine China I in 1 II a control of the control of		
1,	Supplying, fixing and wiring a bell transformer 220 volts to 8, 16, 24,	, 194	5
ight share a	volts, 60 cycles, on a suitable board controlled by a D. P. linked 5 amp.	TAT:	
2	witch protected by a pair of fuses, using necessary accessories ;. Supplying, fixing and wiring call bells, controlled from two different points	No.	4.
*	using suitable special casing twin conductor, bell wire, call pushes,		
100	and accessories.		3
		1 >>	
	B		
T.	1. III. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.		
TD.	stalling yard lights at Central Store Yard, Mysore State Railway, Mysor	re.	
1	Supplying and running single phase sub-mains from the main board to	1	
	the sub-distribution board in the verandah of the stores in 2"×1" T. W.		*
T	2-way casing treated with two coats of shellac varnish, using No. 7/.064		
-	SWG. insulated wire and accessories	R.ft	45
2 '	Supplying, fixing and wiring, S. P. 50 amps. iron-clad service cut outs on		
	the main board at the tapping point for the sub-main, using No. 7/.064		300
	SWG insulated wire and accessories	No.	2"
3	Supplying and running circuit mains for feeding five yard lights on the		
	southern wing in T. W. 2-way casing 2"×1" treated with 2 coats of		
	shellac varnish, using No. 7036 SWG, insulated wire and accessories	R.ft.	140
4	Do do three yard lights on the northern wing,		
	using No. 7/.029 SWG. insulated wire and accessories	22	40
5	Supplying and running circuit mains in \(\frac{3}{4}\)" W. I. pipe with bends, clamps,	- 4	05
6	etc., using No. 7/.036 SWG. insulated wire and accessories	٠,,,	25
·	Do do in §" W. I. pipe using No. 7/.029 SWG. insulated wire and accessories	11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	25
7	Supplying, fixing and wiring 15 amps. D. P. iron clad switches with fuses,	23	20
	on suitable T. W. boards using No. 7/.036 SWG. insulated wire and		
	accessories		1
8	Do . do 10 amp. D. P. iron clad switch with fuses,		
	using No. 7/.029 SWG. insulated wire and accessories	7,7	. 1
9.	Erecting and tarring S. M. Rails to be supplied by the Railway Department	13	9
10	Supplying and fixing 2-pin double cross arm complete with clamp, bolt,		
	etc	27	9.
11	Do do single cross arm complete with clamps,		
7.0	bolts, etc.		2
12	Supplying and fixing insulators with pir s	99	40
13	Do do Guy sets with anchor rod, 7-strand guy wire		
14	and 6 ft. of 2" galvanised guard pipe	Lbs.	5 90
	Supplying and scringing pare copper wire No. 8 B. & S. hard-drawn Supplying, fixing and wiring goose neck fittings complete with clamp,	Tring.	ĐŲ
15	aluminium hood, B. C. lamp holder, Radial wave reflectors, etc., using		· · · · · · · · · · · · · · · · · · ·
	No. 3/.036 SWG. insulated wire, and accessories	No.	8
16	Earthing		Two
		2	

N. B.—The insulated wires to be used should be of 660 volts grade.

M. M. ALI KHAN,
Superintendent.

OFFICE OF THE SUPERINTENDENT, POWER AND LIGHTING, BHADRAVATI.

Abstract Notification dated 9-10th February 1939.

The attention of the public is drawn to the Notification, advertised in the Mysore Gazette, dated 9th February 1939, page 287, Part VI, for the work of Installing Lightning Conductors to the Male and Female Dispensaries at Sagar, Shimoga District.

The last date of receiving tenders in this Office is 3rd March 1939.

K. SUBBA RAO, Superintendent.